
LABEL	X LOCATION	Y LOCATION	DETAILS
A1	0.38 in	0.78 in	M3 threaded hole, down 0.2 in. Intended for attaching the alignment bracket.
A2	3.00 in	0.25 in	
A3	5.63 in	0.78 in	Recommended bolts for attaching the alignment bracket to the spoilboard are low-profile 6 mm M3 screws. Three of them ship with the Othermill, along with the required Allen key (2 mm).
B1	1.69 in	1.44 in	M4 x 0.7 mm threaded hole, down 0.4 in.
B2	1.69 in	3.06 in	Use these holes to attach a spoilboard to the Y bed using the bolts provided with the Othermill.
В3	4.31 in	1.44 in	
B4	4.31 in	3.06 in	

NOTE: The eight bolts that hold the Y bed to the Othermill should never be loosened or tampered with. Doing so could affect the positional accuracy of the mill.



All units inches unless otherwise indicated.

TOP VIEW





OTHERMILL

Y BED OTHERMILL V2 OTHERMACHINE.CO/SUPPORT SUPPORT@OTHERMACHINE.CO

Provided for informational purposes only, subject to change.







OTHERMILL

Y BED OTHERMILL V2 OTHERMACHINE.CO/SUPPORT SUPPORT@OTHERMACHINE.CO

Provided for informational purposes only, subject to change.

